Luminex
NETWORK INTELLIGENCE

GigaCore
ETHERNET SWITCHES

RELEASE NOTES

VERSION 1.2.2

Related products: GigaCore 30i, 16t, 18t, 20t

MADE IN BELGIUM

DOCUMENT INFORMATION

With the release of Firmware 1.2.2 Luminex introduces important fixes which solve potential stability issues on particular AVB applications.

FEATURES:

- No new features are introduced in this release.

BUG FIXES:

- An issue was resolved where MAAP (Mac Address Acquisition Protocol) was not forwarded on all ports.
- A bug was fixed where sometimes 100Mb links were not set as gPTP asCapable on ports 21-24 of a GigaCore 30i.

Luminex